UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.

: 7,428,260 B2

Page 1 of 4

APPLICATION NO. : 10/697853

DATED

: September 23, 2008


INVENTOR(S)

: Daniel Yellin

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In the Drawings:

Delete Drawing Sheet 2 and substitute this figure therefor the drawing should be:



UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.

: 7,428,260 B2

Page 3 of 4

APPLICATION NO. : 10/697853

DATED

: September 23, 2008

INVENTOR(S)

: Daniel Yellin

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In the Specification:

At Column 4, line 57, " $g_1(t)$ " should be -- $g_2(t)$ --.

At Column 4, line 64, " $g_1(t)$ " should be -- $g_2(t)$ --.

At Column 5, line 5, " $g_1(t)$ " should be -- $g_2(t)$ --.

At Column 5, line 6, " $g_1(t)$ " should be -- $g_2(t)$ --.

At Column 5, line 9, "Further-more" should be -- Furthermore --.

At Column 5, line 20, " $\forall k_1 k_2$ " should be -- $\forall k_1 \neq k_2$ --.

At Column 8, line 40, "in-fact" should be -- in fact --.

At Column 8, line 65, "MM" should be -- MAI --.

At Column 11, line 5, " $g_1(t)$ " should be -- $g_1(t)$ --.

At Column 11, line 15, " $g_1(t)$ " should be -- $g_1(t)$ --.

At Column 13, line 10, " $h_1(t)$ " should be -- $h_1(t)$ --.

At Column 13, line 11, " $h_1(t)$ " should be -- $h_1(t)$ --.

At Column 13, line 15, " $h_1(t)$ " should be -- $h_2(t)$ --.

At Column 13, line 34, " $h_1(t)$ " should be -- $h_2(t)$ --.

At Column 13, line 40, " $g_1(t)$ " should be -- $g_1(t)$ --.

At Column 15, lines 17-18, "chip-rate 1=1 equalizer" should be -- chip-rate equalizer --.

UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO. : 7,428,260 B2 APPLICATION NO. : 10/697853

,260 B2 Page 4 of 4 7853

DATED : September 23, 2008 INVENTOR(S) : Daniel Yellin

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In the Claims:

At Column 19, line 21, "MUD_type" should be -- MUD-type --.

Signed and Sealed this

Thirteenth Day of January, 2009

JON W. DUDAS
Director of the United States Patent and Trademark Office